

OBSERVATIONS

- System test carried out in backwash and rinse and service (Stn 4). Test okay.
- Iron level field tested 0.0ppm at time of service.
- Aeration pump and Venturi working well.
- Checked all coils. Replaced faulty coil on backwash valve.
- Media level okay.
- Checked and cleaned pre-filter.
- Checked post filter.
- Air release valve working well.
- 0 backwashes carried out since previous service.
- General housekeeping carried out to filter enclosure.

PARTS USED

1 X N/O COIL

Summary

Filtration system working well with no problems anticipated.

Completed by:

Date: